



So many tools, so little time...











Proactive versus Reactive

Before you choose, take some time to:



build the paradigm for your own UST compliance program



set goals based on that paradigm



Paradigm and Goals



100% compliance



Addressing regulatory citations/agreed orders, etc.



Rebuilding a struggling program



Fewer violations



Reduced compliance costs




Competitive advantage



Integrated with fuel delivery management



In-house or contracted/out sourced







iAuditor









+ Q

Search this site



EDIT LINKS

Compliance Calendar



Site Menu





Remediation File Directory



Tank Charts





Groundwater Protection Plans



● Contacts





Mark Links



Locations



Tracking Sheets



Sump Testing Program

Announcements





Modified


SharePoint 2.0

··· September 13, 2017





Interactive Store Viewer Map





Other SharePoint Functionalities



Excel sheets can be linked and incorporated into the SharePoint site



Familiar Microsoft file structuring



Delegate specific access to each portion of your SharePoint site.



Integration with mobile inspection apps

ENSAFE

Work Orders

WO Tracking Number	Store Number	Date of Request	Items to Address	Service Provider	Due Date	Person Sending WO	WO Status/Date Completed	Days to Respond
2018KM283	Kwik-E Mart 555	7/24/2018	Please mobilize to site to: -Replace PRM ASD -Replace the UNL VRA cap with a low profile cap (if possible) -Address weeping meter under dispenser 9/10	Bart Simpson Maintenance	Urgent Response	Adam Wanta	7/25/2018	1
2018KM284	Kwik-E Mart 524	7/24/2018	Please remove liquid from all spill buckets, STP sumps, and dispenser sumps 1/2, 7/8, and 11/12.	Homers Vac Services	8/3/2018	Adam Wanta	8/2/2018	9
2018KM285	Kwik-E Mart 522	7/24/2018	Please mobilize to site to: -Replace UNL 2 ASD -Remove grime from UNL 2 probe manway to improve drainage.	Flanders Maintenance	Urgent Response	Ric Federico	7/24/2018	0
2018KM286	Kwik-E Mart 658	7/24/2018	Please remove liquid from all spill buckets.	Homers Vac Services	8/3/2018	Adam Wanta	Open	#VALUE!
2018KM287	Kwik-E Mart 758	7/24/2018	Please remove grime from UNL probe manway to improve drainage.	Springfield Pump and Tank	8/3/2018	Ric Federico	Open	#\/Δ Ε
2018KM288	Kwik-E Mart 365	7/24/2018	Please remove liquid from all spill buckets and STP sumps. Please provide waste manifest when work is completed.	Homers Vac Services	8/3/2018	Ric Federico	Open	#WALLIEL
2018KM289	Kwik-E Mart 112	7/25/2018	Please conduct hydrostatic testing on the UDC of dispenser 5/6. Notify EnSafe of the results.	Bart Simpson Maintenance	Urgent Response	Adam Wanta	Open	#WALLIEL
2018KM290								0
2018KM291								0
			1					





Suspected Release Reporting

EnSafe Tracking Number	Location	State	Date & Time of SRR Notification	Date & Time SR Occurred	How SR was found	Reportable Alarm/Event	Product or System	Service Provider Mobilized	Action Taken	SRR Number	Red Tag Placed?	Person Reporting SRR	Notes	SRR Status or Date Closed	Days to Resolve
2018SRR026	Kwik-E Mart 887	???	6/15/18 10:50	6/15/18 8:30	Inform Check by EnSafe	Liquid Sensor Fuel Alarm - Non Discriminating Sensor	Dispenser	Bart Simpson Maintenance	Tech mobilized to check for fuel/water.	12548	No	Adam Wanta	BSM identified a cracked shear valve. Replaced onsite. HVS mobilized to remove liquid.	6/15/2018	0
2018SRR027	Kwik-E Mart 241	???	6/19/18 13:00	6/19/18 9:15	Inform Check by EnSafe	Unexplained Release Detection Alarms	DSL	Homers Vac Services	Product has been bagged off and breaker flipped. Techs mobilized to check for release and troubleshoot alarm.	22356	No	Adam Wanta	HVS investigated and arrived onsite to passing tests.	6/19/2018	0
2018SRR028	Kwik-E Mart 366	???	6/25/18 9:00	6/24/18 20:00	Inform.net Email Alarm	Gross Line Failure	UNL	Flanders Maintenance	Ned mobilized to site and identified a bad STP motor in one of the UNL tanks. They were unable to replace motor so they will remobilize 6/25/18.	22584	No	Adam Wanta	FM replaced STP and reran passing test.	6/26/2018	1
2018SRR029	Kwik-E Mart 564	???	7/1/18 8:30	6/30/18 20:48	Inform Check by EnSafe	Periodic Test Failure	PRM	Homers Vac Services	Tech to mobilize and check for evidence of a release and troubleshoot alarm.	23211	No	Adam Wanta	System passed CSLD.	7/4/2018	3
2018SRR030	Kwik-E Mart Quick Lube 548	???	7/20/18 11:45	7/20/18 11:15	Store Staff Reported	Evidence of a release of a regulated substance	Dispenser	Springfield Pump and Tank	Tech mobilized to site to investigate impact, absorb fuel from storm drain.	24875	No	Ric Federico	Overfill of gasoline at dispenser. Impacted storm drain.	Open	#VALUE!
2018SRR031	Kwik-E Mart 123	???	7/21/18 8:02	7/21/18 12:56	Inform.net Email Alarm	Liquid Sensor Fuel Alarm - Non Discriminating Sensor	PLS	Homers Vac Services	Tech mobilized to site to investigate liquid sensor alarm, remove liquid from sump.	55563	No	Ric Federico		Open	#VALUE!
2018SRR032	Kwik-E Mart 869	???	7/25/18 13:30	7/25/18 12:40	Physical Inspection by Others	Evidence of a release of a regulated substance	Dispenser	Bart Simpson Maintenance	Leak coming from meter under dispenser 5/6. Tech tripped shear valve to stop leak and in process of removing fuel. Estimated 20 to 25 gallons in UDC.	25254	Yes	Adam Wanta	EnSafe requested hydrostatic test on sump.	Open	
2018SRR033		#N/A													0
2018SRR034		#N/A													0

Microsoft Excel (Form Creation and Metrics)









Suspected Release Tracking Form


				,					
EnSafe SRR Tracking	g Number:	2018SRR03	2						
		Fa	cility Inf	ormation					
Location	Kwik-E Mart 869	State	???	Address	1517 Main Street	Springfield			
AI#	548	56		County	Spring	Springfield			
District Manager	Apu Nahasap	eemapetion		District Manager Email	apun@kwik-e_mart.org				
Store Phone Number	555-2	564		DM Phone Number	555-8989				
Notes	Site is known for their slushi	os.							
		E	RT Noti	fication					
SR Incident Number	25254		Date 8	& Time of Notification	7/25/18	13:30			
Person Reporting SR	Adam Wanta		Com	pany Reporting SR	EnS	afo			
Responsible Party	Kwik-E Mart		Respo	nsible Party Address	273 2nd Ave, Shelbyville				
	1-8	00-555-4441 S	pringfield En	nergency Response Brigade					
		Suspect	ed Relea	ase Information					
Product or Line affected?	Dispenser		d Release pe	Evidence of a release of a regulated substance					
Date & Time SR Occurred	7/25/18	12:40		How was SR found? Physical Inspection by Others					
What Response Actions have been taken? Leak coming from meter under dispenser 5/6. Tech tripped shear valve to stop leak and in process of removing fuel. Estimated 20 to 25 gallons in UDC.									
Facility Response Actions	containment), in the envi reported immediately to t using a third party appro-	ronment or po he hotline. The red test meth t must be pro	osing a three ne facility mod. If no le operly clear	eat to the environment is nust investigate the source ak source is determined	this includes free product considered a UST system ce of the leak, make requi and no failed tightness te of all actions taken to res	n release and must be red repairs and re-test st results were			
Notes			-						
Facility Response Timeframe		investigate In	nmediately		ENS	ΛFE			

Mobile Inspection Tools (iAuditor)











Microsoft Outlook (Team/Important Date/Email tracking)

When managing a large number of sites keeping you and your team up to date in real time is key.



Utilize the Task or Calendar function to keep everyone in your team in the know in real time.



Set up a team email account so not one person is the bottleneck.



Create team protocols on how to respond to each situation.

