



*Our Community Partnering  
to Protect Your Community*

Pre- and Post-Conference

Sunday, March 13

2:30-6:00 p.m. Pre-conference Networking Event: Harbor Cruise

3:00-7:00 p.m. Registration, Metropolitan Ballroom Foyer

3:00-7:00 p.m. UST Inspector Training Module Demo, Aspen

# 17<sup>th</sup> Annual UST/LUST NATIONAL CONFERENCE



*Our Community Partnering  
to Protect Your Community*

Monday, March 14

7:00 to 8:30	Conference Registration/ Information Desk Open, Second Floor			
8:00 to 10:00	Breakfast Plenary, Grand Ballroom C			
10:00 to 10:30	Break, Grand Ballroom Foyer			
	Prevention	Cleanup	Policy Direction Program Management	Workshops
	Lead: Marshall Mott-Smith, FL Sessions in Grand Ballroom A	Lead: Richard Spiese, VT All Sessions in Grand Ballroom B	Lead: Kara Sergeant, NEIWPCC All Sessions in Metropolitan Ballroom	Lead: Pete Chace, OH All Sessions in West Ballroom
10:30 to 12:00	UST Systems Studies	Small Releases Add Up To Big Problems	Compliance Tools	Brownfields Grants 101: Show Me The Money
12:00 to 1:30	Lunch (on your own)			
1:30 to 3:00	Vapor Releases	Site Evaluation Methodologies	Paying For Cleanups	Reducing The Environmental Impact And Life-cycle Costs Of UST Systems Using An Environment Management System
3:00 to 3:30	Break, Grand Ballroom Foyer			
3:30 to 5:00	A "Hole" New Look At Corrosion	Indoor Air Issues	Managers Caucus  State Managers: Metropolitan Ballroom  Tribal Managers: East Ballroom A	Cathodic Protection Testing Workshop
5:00 to 7:00	UST/LUST Expo Kickoff			
	<b>Meetings:</b>  8:00-5:00 p.m., UST Inspector Training Module, Aspen  3:30-5:00 p.m., EPA Managers Meeting, East Ballroom B			



*Our Community Partnering  
to Protect Your Community*

Tuesday, March 15

8:00 to 5:00	UST/LUST Expo, Grand Ballroom Foyer			
	Prevention	Cleanup	Policy Direction Program Management	Workshops
	Lead: Marshall Mott-Smith, FL Sessions in Grand Ballroom A	Lead: Richard Spiese, VT All Sessions in Grand Ballroom B	Lead: Kara Sergeant, NEIWPCC All Sessions in Metropolitan Ballroom	Lead: Pete Chace, OH All Sessions in West Ballroom
8:00 to 8:30	P3: Petroleum Pipe Phenomen	Streamlining And Prioritizing Cleanups	Linking USTs/LUSTs To Drinking Water	Petroleum Brownfields Program Management Tools
9:30 to 10:00	Break			
10:00 to 11:30	New USTs: The Latest in Design, Monitoring, and Testing	Evaluating Cleanups	Data Management	Behind The Scenes Development For Conferences, Etc.
10:00 to 11:30	Tribal/EPA Managers Meeting, East Ballroom A			
11:30 to 1:30	Luncheon - (speakers TBD) Grand Ballroom C			
1:30 to 3:00	S2: Secondary Containment and Spill Buckets	Cleanup Technologies/Media	Streamlining Cleanups	Community Outreach/EJ
3:00 to 3:30	Break			
1:30 to 3:00	Fuels Quality	Closure Goals: Success Stories	Financial Responsibility	Tribal Issues Workshop/Roundtable
	<b>Meetings:</b> 8:00-5:00 p.m., UST Inspector Training Module, Aspen 1:30-5:00 p.m., Site Revitalization Field Trip			



*Our Community Partnering  
to Protect Your Community*

Wednesday, March 16

	Prevention	Cleanup	Policy Direction Program Management	Workshops
	Lead: Marshall Mott-Smith, FL Sessions in Grand Ballroom A	Lead: Richard Spiese, VT All Sessions in Grand Ballroom B	Lead: Kara Sergeant, NEIWPCC All Sessions in Metropolitan Ballroom	Lead: Pete Chace, OH All Sessions in West Ballroom
8:00 to 9:30	Inspector Think Tank	Oxygenates: Out Of The Fuel, Now Out Of The Groundwater	State/EPA Managers Meeting	Review LUST Corrective Action Technical Documents Using Desktop GIS
9:30 to 9:45	Break			
9:45 to 11:15	UST System Disaster Response: Lessons Learned	Brownfields Case Studies	Regulator/Industry Roundtable	Web-based Applications to Determine Cleanup Levels
11:15 to 11:30	Break			
11:30 to 1:00	SOC	Lead Scavengers: Houston, Do We Have A Problem?	Enforcement	Web-based Training
<b>Meetings:</b>  <b>Wednesday, March 16</b> 8:00-5:00 p.m., UST Inspector Training Module, Aspen 2:00-6:00 p.m., NWGLDE Meeting, East Ballroom A  <b>Thursday, March 17</b> 8:00 a.m.-5:00 p.m., NWGLDE Meeting, East Ballroom A  <b>Friday, March 18</b> 8:00 a.m.-5:00 p.m., NWGLDE Meeting, Cirrus				

Thursday, March 17

8:00 a.m.-5:00 p.m., NWGLDE Meeting, East Ballroom A

Friday, March 18

8:00 a.m.-5:00 p.m., NWGLDE Meeting, Cirrus